

# Feed Throats

**NEW!!!**

**REBUILT!!!**

**REPAIRED!!!**

*Call us to discuss the lower cost, reduced maintenance feed throat design recommendations available to you only through Glycon.*

912 Industrial Drive  
Tecumseh, MI 49286  
Phone: 800-255-9969  
Fax: 517-423-7470



## **Feed Throat repair services and manufactured components include:**

- Re-lining your current feed throat housing with grooved or smooth bore one piece constructed industry standard carbide liner.
- Re-designing your current, feed throat housing to accommodate Glycon's 2-piece welded liner assembly. The Glycon design does not rely on an "interference fit" between the liner and housing to contain cooling fluids. Unlike the 1-piece design, once you have the Glycon liner, the 2-piece design is self supporting and allows the customer to press out a worn Glycon design liner and install a new or refurbished liner.
- Exploring the possibility of going from a grooved feed design to a smooth bore feed throat, in combination with Glycon's DM2 high performance feedscrew, to approach grooved feed extrusion rates while eliminating accelerated wear issues inherent to grooved feed systems.
- Providing a low cost domestic source for feed throat maintenance to fit most plastic processing machinery.

